

Tips from Comanche *Flyer* magazines Feb 1973 – Sep 2012

## CHAPTER FOURTEEN

### AD COMPLIANCE (AD LISTING ALL PA24 / PA30-39 AIRCRAFT)

#### Table of Contents

|  |    |
|--|----|
| Comanche 180 AD List .....   | 2  |
| Comanche 250 AD List .....   | 4  |
| Comanche 260 AD List .....   | 6  |
| Comanche 400 AD List .....   | 8  |
| Twin Comanche AD List.....   | 9  |
| Twin Comanche C/R AD List.....   | 11 |
| Search for ADs on FAA's Internet site .....  | 12 |
| AD Search and Update Procedure.....  | 12 |
| AD 77-13-21 (Jan 2004).....  | 13 |
| Visual Inspection- what does that mean? (Feb 2005).....  | 13 |
| AD 94-13-10 (amendment 39-8951) which superceded AD 74-13-01 (amendment 39-1870) (Sep 2011)..... | 14 |
| AD Listing (Feb 2012) .....  | 14 |

As I get many requests for a list of the AD notes, space permitting. Please remember that this is not a complete listing of all ADs which may apply to your aircraft. There are ADs on beacons, radios, ELTs and many other items which may be in your aircraft and we have no way of knowing which of these items you have. This listing is the primary ones from Piper, Lycoming, Hartzell, McCauley and Bendix. Maurice Taylor Technical Director

## **Comanche 180 AD List**

| <b>AD #:</b> | <b>PIPER PA-24-180</b>   |
|--------------|--|
| 58-25-05     | Door latch modification  |
| 59-06-05     | Nose gear bungee   |
| 59-07-05     | Oil cooler line clearance  |
| 59-12-09     | Control wheel sprocket stud  |
| 59-13-02     | Aileron balance weight   |
| 59-26-02     | Two fuel cell vent tubes   |
| 60-24-03     | Fuel vent tubes  |
| 61-16-06     | Fuel selector valve handles  |
| 62-10-03     | Aileron counterweight bay rework   |
| 62-26-05     | Exhaust system   |
| 63-27-03     | Landing gear retraction motor circuit  |
| 64-22-03     | Landing gear safety switch   |
| 65-25-03     | Nose landing gear drag link clevis   |
| 68-05-01     | Exhaust mufflers   |
| 68-13-03     | Fuel cell collapse   |
| 72-22-05     | Operation limitation placard   |
| 74-13-03     | Stabilator attach bolts  |
| 75-05-02     | Engine oil   |
| 75-12-06     | Fin forward spar   |
| 75-27-08     | Torque tube bearing fittings   |
| 77-08-01     | Aileron spar cracks  |
| 77-13-21     | Prevent landing gear collapse  |
| 79-20-10     | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 82-23-01 R1  | Placard near flap actuator   |
| 83-19-03     | Lower spar cap inspection  |
| 85-02-05 R1  | P/N 683-107 placard installation (supersedes P/N 81090-02)                               |
| 94-13-10     | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1  | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 98-21-21 R1  | Bob Fields Aerocessories Inflatable door seals (supersedes 98-21-21)                     |
| 99-05-09     | Induction Air Filter   |

|              |                                  |
|--------------|----------------------------------|
| <b>AD #:</b> | <b>LYCOMING Engine O-360-A1A</b> |
| 59-10-07     | Cylinder baffle clamps           |
| 64-16-05     | AC fuel pumps                    |
| 66-20-04     | AC oil filters                   |
| 73-23-01     | Lyc. overhauled engine           |
| 75-08-09     | Oil pump gears                   |
| 79-10-03R2   | Engine mount bolts               |
| 79-15-02     | Carburetor channel plug          |
| 80-04-03R1   | Valve spring seats               |
| 80-14-07     | Valve spring seats               |
| 81-18-04R2   | Sintered impellers               |
| 87-10-06     | Rocker arm assembly              |
| 90-04-06R1   | Governor oil line                |
| 91-14-22     | Propeller strike                 |
| 92-12-05     | Piston pin failure               |
| 92-15-16     | Carburetor float                 |
| 93-05-21     | Overhauled fuel pump             |
| 93-11-11     | Overhauled fuel pump             |
| 93-19-04     | Supersedes 92-15-16              |
| 94-14-13     | Bad Fuel                         |
| 96-09-10     | Oil Pump (81-18-04R2)            |
| 98-17-11     | Crankshafts                      |
| 2004-10-14   | Crankshaft gear                  |
| 2006-06-16   | Crankshaft                       |
| 2006-12-07   | ECi cylinder assemblies          |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>BENDIX Magnetos S4LN-20 and S4LN-21 AD's</b>                       |
| 73-07-04     | Coil  |
| 73-10-02     | Servo unit -DNA to 180  |
| 74-26-09     | Drive shaft   |
| 76-07-12     | Rotary switch   |
| 78-09-07     | R3 Coupling   |
| 79-21-08     | Servo unit - DNA to 180   |
| 82-13-01     | Distributor block   |
| 82-20-01     | Impulse coupling  |
| 94-01-03     | R1/R2 Magneto update  |
| 94-06-09     | Non-grounded magneto  |
| SB #599D     | Coupling wear rate  |
| 96-12-07     | Impulse Coupling  |
| 2005-12-06   | Riveted-impulse coupling assemblies and snap-ring coupling assemblies |

|              |                                      |
|--------------|--------------------------------------|
| <b>AD #:</b> | <b>HARTZELL Propeller HC-92ZK-8D</b> |
| 60-16-04     | Guide collars                        |
| 73-02-01     | Blade inspection                     |
| 95-11-08     | Blade Inspection                     |
| 2005-18-12   | "Z-shank" blade                      |

|              |                                     |
|--------------|-------------------------------------|
| <b>AD #:</b> | <b>MCCAULEY Propeller: 2D36C 14</b> |
| 64-24-04     | Cracks blade shank                  |
| 70-04-01     | Blade failure                       |
| 77-16-01     | Prop modification                   |
| 2005-14-11   | Failed propeller blade              |

## **Comanche 250 AD List**

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>PIPER PA-24-250</b>   |
| 59-06-05     | Nose gear bungee   |
| 59-12-09     | Control wheel sprocket stud  |
| 59-13-02     | Aileron balance weight   |
| 59-26-02     | Two fuel cell vent tubes   |
| 60-24-03     | Fuel vent tubes  |
| 61-16-06     | Fuel selector valve handles  |
| 61-20-02     | Exhaust stack reinforcement  |
| 62-10-03     | Aileron counterweight bay rework   |
| 62-26-05     | Exhaust System   |
| 63-27-03     | Landing gear retraction motor circuit  |
| 64-10-04     | Carburetor air box deflector vanes   |
| 64-22-03     | Landing gear Safety Switch   |
| 65-11-04     | Stabilator control system  |
| 65-25-03     | Nose landing gear drag link clevis   |
| 68-05-01     | Exhaust mufflers   |
| 68-13-03     | Fuel cell collapse   |
| 72-22-05     | Operation limitation placard   |
| 74-13-03     | Stabilator attach bolt   |
| 75-05-02     | Engine oil   |
| 75-12-06     | Fin forward spar   |
| 75-27-08     | Torque tube bearing fittings   |
| 76-19-07     | Stabilator weightt assembly  |
| 77-08-01     | Aileron spar cracks  |
| 77-13-21     | Prevent landing gear collapse  |
| 79-20-10     | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 82-23-01 R1  | Placard near flap actuator   |
| 83-19-03     | Lower spar cap inspection  |
| 85-02-05     | P/N 81090-2 placard installation   |
| 85-02-05 R1  | P/N 81090-2 placard installation (supersedes P/N 81090-02)                               |
| 94-13-10     | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1  | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 99-05-09     | Induction air filter   |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>LYCOMING Engine O-540-A1A</b>            |
| 59-10-07     | Cylinder baffle clamps                      |
| 63-14-03     | Oil pump shaft                              |
| 64-16-05     | AC fuel pump                                |
| 66-14-03     | Oil pump                                    |
| 66-20-04     | AC oil filter                               |
| 73-23-01     | Overhauled engines                          |
| 75-08-09     | Oil pump                                    |
| 81-18-04R2   | Sintered gear                               |
| 87-10-06R1   | Rockerarm                                   |
| 91-08-07     | Turbo models                                |
| 91-14-22     | Prop Strike                                 |
| 92-12-05     | Piston pin failure                          |
| 92-15-16     | Carburetor float                            |
| 93-02-05     | Injector fuel lines                         |
| 93-05-21     | Overhauled fuel pump                        |
| 93-11-11     | Overhauled fuel pump                        |
| 93-19-04     | Supersedes 92-15-16                         |
| 94-14-13     | Bad Fuel (95-26-02)                         |
| 96-06-10     | Lyc Turbo                                   |
| 96-09-10     | Oil Pump                                    |
| 2004-05-24   | Zinc-plated Crankshaft Gear Retaining Bolts |
| 2004-10-14   | Crankshaft gear                             |
| 2006-12-07   | ECi cylinder assemblies                     |

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>BENDIX Magnetos S6LN-20 and S6LN-21</b>           |
|              | Note Bendix Mag AD's are all the same. See PA-24-180 |

|              |                                      |
|--------------|--------------------------------------|
| <b>AD #:</b> | <b>HARTZELL Propeller HC82XK-1 D</b> |
| 53-15-03     | Pitch link screws                    |
| 58-06-02     | Split rings                          |
| 58-07-01     | Split rings                          |
| 58-09-02     | Piston guide rod                     |
| 59-01-03     | Split rings                          |
| 59-09-03     | Mounting bolts                       |
| 60-16-04     | Guide collars                        |
| 68-19-04     | Blade inspection                     |
| 85-14-1OR2   | Blade Clamps                         |
| 97-18-02R1   | Prop Inspection                      |

|              |                                     |
|--------------|-------------------------------------|
| <b>AD #:</b> | <b>MCCAULEY PROPELLER: 2D36C28:</b> |
| 64-24-04     | Cracks blade shank                  |
| 70-04-01     | Blade failure                       |
| 77-16-01     | Prop modification                   |
| 2005-14-11   | Failed propeller blade              |

|              |                      |
|--------------|----------------------|
| <b>AD #:</b> | <b>TURBOCHARGER</b>  |
| 81-19-04     | Hoses                |
| 82-27-03     | Cracked turbocharger |

|              |                             |
|--------------|-----------------------------|
| <b>AD #:</b> | <b>AUTOPILOT (MITCHELL)</b> |
| 70-15-18     | Bridle Cable Clamp          |

## **Comanche 260 AD List**

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>PIPER PA-24-260</b>   |
| 65-11-04     | Stabilator control system  |
| 66-18-04     | Baggage door latch   |
| 68-05-01     | Exhaust mufflers   |
| 71-12-05     | Electric trim switch modification  |
| 72-22-05     | Operation limitation placard   |
| 74-13-03     | Stabilator attach bolts  |
| 75-05-02     | Engine oil   |
| 75-12-06     | Fin forward spar   |
| 75-27-08     | Torque tube bearing fittings   |
| 76-19-07     | Stabilator weight assembly   |
| 77-08-01     | Aileron spar cracks  |
| 77-09-10     | Electric trim switch   |
| 77-13-21     | Prevent landing gear collapse  |
| 79-20-10     | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 82-23-01 R1  | Placard near flap actuator   |
| 83-19-03     | Lower spar cap inspection  |
| 85-02-05     | P/N 81090-2 placard installation   |
| 85-02-05 R1  | P/N 683-107 placard installation (supersedes P/N 81090-02)                               |
| 91-21-09     | Induction heat   |
| 94-13-10     | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1  | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 98-21-21 R1  | Bob Fields Aeroaccessories Inflatable door seals (supersedes 98-21-21)                   |
| 99-05-09     | Induction Air Filter   |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>LYCOMING Engine (IO-540 E4A5 and IO-540-R1A5 Turbo</b> |
| 63-14-03     | Oil pump shaft  |
| 64-16-05     | AC fuel pump  |
| 66-20-04     | AC oil filter   |
| 67-22-06     | Bendix injector   |
| 69-08-09     | Placard   |
| 73-23-01     | Lyco overhauled engines                                   |
| 75-08-09     | Oil pump  |
| 75-09-15     | Fuel injector   |
| 78-23-08     | Fuel line leak  |
| 81-03-05     | Bendix injector   |
| 81-18-04     | Sintered gear   |
| 83-22-04     | Bendix injector   |
| 87-10-06     | Rocker arm  |
| 91-08-07     | Fuel pump vent turbos                                     |
| 91-14-22     | Propeller strike  |
| 92-12-05     | Piston pin failure  |
| 92-15-16     | Carburetor float  |
| 92-20-07     | Modified fuel pumps                                       |
| 93-02-05     | Fuel injection lines                                      |
| 93-05-21     | Overhauled fuel pump                                      |
| 93-11-11     | Overhauled fuel pump                                      |
| 93-19-04     | Supersedes 92-15-16                                       |
| 94-14-13     | Bad fuel  |

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>BENDIX Magnetos S6LN-204 and -200 in normally aspirated engine and S6LN-1208 and -1209 in turbo model</b> |
|              | Note Bendix Mag AD's are all the same. See PA-24-180   |

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>HARTZELL Propeller HC C2YK-1A &amp; -1B, and HC E2YR-1B</b> |
| 64-20-01     | Pitch change blocks  |
| 71-21-09     | Spring Backup Kit  |
| 2002-09-08   | Blade shank cracks (supercedes AD 77-12-06)                    |
| 2003-03-20   | Propeller hubs   |
| 2003-06-02   | Anti-ice boots   |
| 2003-13-17   | Propeller blade  |
| 2006-18-15   | Front cylinder half of the propeller hub                       |
| 2006-24-07   | Propeller blades   |

|              |                      |
|--------------|----------------------|
| <b>AD #:</b> | <b>TURBOCHARGER</b>  |
| 81-19-04     | Hoses                |
| 82-27-03     | Cracked turbocharger |

|              |                             |
|--------------|-----------------------------|
| <b>AD #:</b> | <b>AUTOPILOT (MITCHELL)</b> |
| 70-15-18     | Bridle Cable Clamps         |

## **Comanche 400 AD List**

|              |  |
|--------------|--|
| <b>AD #:</b> | <b>PIPER PA-24-400</b>   |
| 65-11-04     | Stabilator control system  |
| 66-30-07     | Fuel purge valve hose assembly   |
| 74-13-03     | Stabilator attach bolts  |
| 75-12-06     | Fin forward spar   |
| 75-27-08     | Torque tube bearing fittings   |
| 77-08-01     | Aileron spar cracks  |
| 77-13-21     | Prevent landing gear collapse  |
| 79-12-08     | Fuel selector valves   |
| 79-20-10     | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 83-10-01     | Water and fuel system inspection   |
| 83-19-03     | Lower spar cap inspection  |
| 85-02-05     | Piper P/N 81090-02 placard installation  |
| 85-02-05 R1  | P/N 683-107 placard installation (supersedes P/N 81090-02)                               |
| 94-13-10     | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1  | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 98-21-21 R1  | Bob Fields Aeroaccessories Inflatable door seals (supersedes 98-21-21)                   |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>LYCOMING Engine IO-720-A1A or -A1B</b> |
| 73-23-01     | Lycoming overhauled engines               |
| 75-09-15     | Fuel injector                             |
| 91-08-07     | Turbo models                              |
| 91-14-22     | Prop strike                               |
| 92-12-05     | Piston pin failure                        |
| 93-02-05     | Fuel Injection lines                      |
| 93-11-11     | Overhauled fuel pump                      |
| 94-14-13     | Bad fuel                                  |
| 95-26-02     | Supersedes 94-14-13                       |
| 96-23-03     | Hi Pressure Fuel Pump                     |
| 98-18-12     | Rotary Fuel Pump                          |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>BENDIX MAGNETOS S8LN-701 and -705 in -A1A Engine<br/>S8LN-1208 and -1209 in A1B Engine</b> |
|              | AD's are same for all Bendix Magnetos. See PA-24-180  |

|              |                                     |
|--------------|-------------------------------------|
| <b>AD #:</b> | <b>HARTZELL Propeller HC-A3VK-4</b> |
| 68-19-04     | Blade inspection                    |
| 85-14-10R2   | Blade clamps                        |

|              |                            |
|--------------|----------------------------|
| <b>AD #:</b> | <b>RAJAY Turbochargers</b> |
| 81-19-04     | Hoses                      |
| 82-27-03     | Cracked turbocharger       |



|              |                           |
|--------------|---------------------------|
| <b>AD #:</b> | <b>MITCHELL Autopilot</b> |
| 70-15-18     | Bridle Cable Clamps       |

## **Twin Comanche AD List**

| <b>PIPER AD #:</b> | <b>PIPER PA-30</b>   |
|--------------------|--|
| 64-09-05           | Induction system alternate air doors   |
| 64-16-06           | Nose gear retraction tubes   |
| 64-21-05           | Hartzell propeller governor  |
| 64-28-03           | Heavy walled torque tube (supersedes 64-16-07)   |
| 65-11-04           | Stabilator control system  |
| 66-18-04           | Baggage door latch   |
| 66-28-06           | Stabilator system (supersedes 66-12-02)  |
| 67-19-05           | Oxygen cylinder mounting channels  |
| 69-13-03           | Heater exhaust tube  |
| 69-24-04           | Minimum control speed  |
| 70-15-17           | Operation limitation placard   |
| 70-22-05           | Electrical system modifications  |
| 71-12-05           | Electric trim switch modification  |
| 74-13-03           | Stabilator attach bolts  |
| 74-16-08           | Aft bulkhead assembly  |
| 75-27-08           | Torque tube bearing fittings   |
| 76-18-05           | Forward fin attachment   |
| 77-08-01           | Aileron spar cracks  |
| 77-09-10           | Electric trim switch   |
| 77-13-21           | Prevent landing gear collapse  |
| 78-12-07           | Fuel selector valve  |
| 79-12-08           | Fuel selector valves   |
| 79-20-10           | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 82-23-01 R1        | Placard near flap actuator   |
| 83-10-01           | Water and fuel system inspection   |
| 83-19-03           | Lower spar cap inspection  |
| 85-02-05           | P/N 81090-2 placard installation   |
| 85-02-05 R1        | P/N 683-107 placard installation (supersedes P/N 81090-02)                               |
| 94-13-10           | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1        | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 98-21-21 R1        | Bob Fields Aerocessories Inflatable door seals (supersedes 98-21-21)                     |
| 99-14-01           | AFM - Limitations Section - Icing (supersedes 98-04-27)                                  |

|              |   |
|--------------|---|
| <b>AD #:</b> | <b>LYCOMING ENGINE IO-320-B1A In C/R models: IO-320-B1A (LH) and LIO-320-B1A (RH)</b> |
| 64-16-05     | AC fuel pump  |
| 65-03-03     | Crankshaft flange   |
| 66-20-04     | AC oil filters  |
| 67-22-06     | Bendix injector   |
| 73-23-01     | Overhauled engines  |
| 75-08-09     | Oil pump gears  |
| 75-09-15     | Fuel injector   |
| 87-10-06R1   | Rocker arm  |
| 95-26-02     | Aviation gasoline   |
| 96-09-10     | Oil Pump  |
| 96-23-03     | High Pressure Fuel Pumps  |
| 98-02-08     | Crankshaft  |
| 98-17-11     | Crankshaft  |
| 2002-26-01   | Fuel Injector Fuel Lines  |
| 2003-14-03   | Rotary Fuel Pumps   |
| 2004-10-14   | Crankshaft Gear   |

|  |   |
|--|---|
| <b>AD #:</b>   | <b>HARTZELL Propellers: HC-E2YL-2A, 2BS, 2c, 2D, 2BSF</b> |
| PROPELLER AD's are the same for TURBO and NORMALLY ASPIRATED TWINS |   |
| 64-20-01   | Pitch change blocks                                       |
| 71-21-09   | Overspeed modification                                    |
| 2003-13-17   | Propeller blade   |
| 2006-24-07   | Propeller blade   |

|             |   |
|-------------|---|
| <b>AD #</b> | <b>BENDIX Magneto S4LN-20 and S4LN-21</b>             |
|             | Note- Bendix Mag AD's are all the same. See PA-24-180 |

|              |                           |
|--------------|---------------------------|
| <b>AD #:</b> | <b>RAJAY Turbocharger</b> |
| 81-19-04     | Hose replacement          |
| 82-27-03     | Cracks                    |

|               |   |
|---------------|---|
| <b>AD #</b>   | <b>HEATERS (Both JANITROL and STEWART-WARNER (SOUTHWIND))</b> |
| 81-09-09      | Combustion heater   |
| 82-07-03      | Combustion heater   |
| 2004-25-16 R1 | Fuel regulator shutoff valves                                 |

## **Twin Comanche C/R AD List**

| <b>AD #:</b> | <b>PIPER PA-39</b>   |
|--------------|--|
| 71-12-05     | Electric trim switch mod   |
| 74-13-03     | Stabilator attach bolts  |
| 74-16-08     | Aft bulkhead assembly  |
| 75-27-08     | Torque tube bearing fittings   |
| 76-18-05     | Forward fin attachment   |
| 77-08-01     | Aileron spar cracks  |
| 77-09-10     | Electric trim switch   |
| 77-13-21     | Prevent landing gear collapse  |
| 78-12-07     | Fuel selector valve  |
| 79-12-08     | Fuel selector valves   |
| 79-20-10     | Aileron nose rib reinforcement<br>Piper Kit Part No. 763 893<br>(supersedes AD 74-10-03) |
| 82-23-01 R1  | Placard near flap actuator   |
| 83-10-01     | Water and fuel system inspection   |
| 83-19-03     | Lower spar cap inspection  |
| 85-02-05     | Piper P/N 81090-02 placard   |
| 85-02-05 R1  | P/N 683-107 placard installation (supersedes P/N 81090-02)                               |
| 94-13-10     | Stabilizer Torque Tube (Hi-Shear rivet replacement kit) (supersedes 74-13-01)            |
| 97-01-01 R1  | Main gear sidebrace stud (supersedes 97-01-01 which superseded 95-20-07)                 |
| 98-21-21 R1  | Bob Fields Aeroaccessories Inflatable door seals (supersedes 98-21-21)                   |
| 99-14-01     | AFM - Limitations Section - Icing (supersedes 98-04-27)                                  |

| <b>AD #:</b>   | <b>LYCOMING ENGINE IO-320-C1A (LH) and LIO-320-C1A (RH)</b> |
|--|---|
| TURBO ENGINE AD's (Note- Normally Aspirated Engine AD's are the same as for PA-30) |   |
| 66-20-04   | AC oil filters  |
| 67-22-06   | Bendix injector   |
| 73-23-01   | Overhauled engines  |
| 75-08-09   | Oil pump gears  |
| 75-09-15   | Fuel injector   |
| 87-10-06R1   | Rocker arm  |
| 95-26-02   | Aviation gasoline   |
| 96-09-10   | Oil pump  |
| 96-23-03   | High pressure fuel pumps                                    |
| 98-02-08   | Crankshaft  |
| 2002-26-01   | Fuel injector fuel lines                                    |
| 2003-14-03   | Rotary fuel pumps   |
| 2004-10-14   | Crankshaft gear   |
| 2006-12-07   | ECi cylinder assemblies                                     |

| <b>AD #</b> | <b>BENDIX Magneto S4RN-20 and S4RN-21</b>            |
|-------------|--|
|             | Note Bendix Mag AD's are all the same. See PA-24-180 |

## Search for ADs on FAA's Internet site

We are not aware of any way to type in a few parameters into your computer, push a button, and get a complete and current AD List for your aircraft. As stated at the beginning of this chapter, the AD Lists we have provided are meant to be a jumping off point to get you started on your own AD Search. Don't use our lists as anything more than that. These lists can be out of date three days from now. The only certainty is that they will change. Some AD's will disappear from the lists as they are superseded by newer Airworthiness Directives.

There is no such thing as a "standard Comanche." Even when new, most Comanches differed from others of the same model because they had been ordered with different accessories. In the ensuing 40+ years, some owners have changed their Bendix magnetos for ones made by Slick. Other accessories such as alternators, starters, radios, etc., have been substituted for the original equipment. In short, there is no way that you can get a "one-stop" list of the AD's that affect your airplane. In order to help you prepare your own personalized AD list, we have outlined the procedure that we use.

## AD Search and Update Procedure

This should be done at each annual inspection.

1. Record the model number and serial number for your aircraft and engine model number, *e.g.*, PA-30, S/N PA 30-1231, and Lycoming IO-320-B1A.
2. Record the model numbers for your props, magnetos, Janitrol heater, autopilot, turbochargers, *etc.* Record the serial number if that part has one.
3. Make a list of everything in your airplane that has been installed such as radios, autopilots, navigational equipment, strobes, inflatable door seals, brakes, *etc.* Include in this list any equipment that was not on the plane when it was new. Keep all this information with your logbooks so you don't have to repeat this part next year.
4. The part numbers for your engines and your props will be in your logbooks. If you still have the original equipment magnetos, you can find your mags by going to the FAA website at <http://faa.gov>. Look up TCDS's (Type Certificate Data Sheets) and go to Lycoming and locate the model number of your engine. Near the end of the data sheet you will find your mag model number listed under ignition system. Note that you can also look in the TCDS's for your particular aircraft under Piper and display the standard equipment list for that plane.
5. Once you are armed with the manufacturer and part number for each item in your plane, you can do an AD search by clicking on the AD section at the FAA site. For example, if you check on the Lycoming engine IO-320-B1A, it will list all the AD's in chronological order which pertain to that engine. The FAA does not know that you installed a new B&C lightweight starter or an InterAv alternator, so you are going to have to go to those manufacturer sections and look for your part number for AD's affecting those accessories.
6. Likewise when you do a yearly check on your aircraft model's AD's, don't expect your Janitrol heater AD's to be there. You will have to check under Janitrol, but in the process, you learn that those heaters are now serviced by Kelly Aerospace Power Systems. Make a note of the new company and next year you won't spend time looking for Janitrol in the manufacturer's list.
7. You will greatly help your A&P/IA mechanic if you keep track of the AD's on your airplane. If you are the owner of record on your aircraft and many of its accessories, you will receive AD's from the FAA by mail. Save these in a folder and better still make a copy of them for your mechanic. He does not automatically get a copy of these individual AD's. He probably subscribes to a service where he receives updates on a CD, but he will have to hunt for your AD's among hundreds of others. Admittedly, he is going to do his own AD search, but you are in a position to be more familiar with the equipment and modifications on your plane than he is.
8. Most mechanics will put a list of AD's that pertain to each entity in the back of your aircraft logs, your engine logs, propeller logs, *etc.* These lists will make it much easier to keep track of when and how an AD has been complied with, or when it needs to be done again, such as a recurring inspection or replacement, *e.g.*, the bungees on the landing gear.
9. Once you have all your Comanche's AD's researched, complied with, and documented, it will be much easier to perform an update next year.

## AD 77-13-21 (Jan 2004)

**Q** I own a 1966 PA30B with Miller Conversion. I recently changed A&P mechanics and am scheduling a new annual that is due by the end of this month. My new mechanic tells me that Part “A” of AD 77-13-21 has not been accomplished within the last 1,000 hours and is now required. Evidently my old mechanic never addressed Part “A” of the AD, only Part “B,” which was the replacement of the bungees, which has been done twice since I have owned the aircraft.

Does Part “A” of the AD apply to my aircraft? My new mechanic says this is an extensive AD, which requires the dismantling of the complete landing gear assembly and measurement of different components. Thank you for your input in this manner.

**A** This AD applies to ALL Comanches except as noted, a single PA-24-400 serial No. 1, which was a test aircraft. Part (a) requires disassembly of the landing gear and testing clearances with go and no-go gauges. These gauges are available on loan from ICS Headquarters. I have reprinted the AD for you to read. The service letter referred to in part (a) is what really spells out the work that needs to be done. It is far too extensive to reprint here. Your mechanic probably has approach Tdata on CD disc. The service letter is available there. Sections (a) and (c) of this particular AD are probably the most overlooked of all Comanche ADs. I suspect the reasoning by most mechanics is that the majority of our Comanches are utilized as cross country-traveling machines. The gear cycles only twice in the course of a flight that may vary from an hour to possibly six or more hours. However, if the aircraft is used as a trainer, there may be as many as a dozen gear cycles in an hour when practicing takeoffs and landings. This would obviously cause a lot more wear. The FAA always looks for worse case scenarios when demanding ADs. The trainer would have maybe 12,000 gear cycles in 1,000 hours. The cross-country machine would have 330 gear cycles in 1,000 hours based on average three-hour flights. The trainer scenario aircraft would need service to the gear much more frequently than the cross-country machine.

### **77-13-21 PIPER AIRCRAFT CORPORATION:**

Amendment 39-2946 as amended by Amendment 39- 3093. Applies to airplane models PA-24, PA-24-250, and PA-24-260; model PA-24-400, except S/N 1; and models PA-30 and PA-39, certificated in all categories.

For aircraft having 1,000 hours or more in service on the effective date of this AD, compliance is required within the next 100 hours in service, and for aircraft having less than 1,000 hours in service, compliance is required prior to 1,100 hours in service, unless already accomplished in either case. To prevent collapse of the landing gear after manual extension;

(a) Accomplish the inspection described on page 3 of Piper Aircraft Corporation Service Letter No. 782A, dated March 21, 1977, and replace components exceeding the specified wear limits, or an equivalent inspection and replacement procedure approved by the Chief, Engineering and Manufacturing Branch, FAA Eastern Region.

(b) Inspect the main landing gear bungee cords for frayed protective covering, breaks, soft areas, and replace cords exhibiting these conditions. In addition, replace cords every 500 hours in service, or every three years, whichever occurs first.

(c) Repeat paragraph (a) at each 1,000 hours in service after the prior inspection, and repeat paragraph (b) at each 500 hours in service after the prior inspection, or within one year after the prior inspection, whichever occurs first.

## Visual Inspection- what does that mean? (Feb 2005)

**Q** What does it mean when an AD was complied with by “visual inspection?”

**A** Many Airworthiness Directives require “visual inspections” to determine if a faulty condition exists. Using the AD instructions, some of these visual inspections can be done by the pilot/owner while others require a certificated Airframe and Powerplant mechanic to do the inspection.

Visual inspections may require only sharp vision, while others specify a certain power of magnifying glass or special inspection lights/tools (borescopes, mirrors, etc). They are generally basic inspections not requiring sophisticated non-destructive testing procedures or tools. The best inspections are done by people with strong powers of observation, whether they are certificated or not. Many of the one-time (non-repetitive) AD's issued to the Comanche are worth giving another look as our fleet ages.

## **AD 94-13-10 (amendment 39-8951) which superceded AD 74-13-01 (amendment 39-1870) (Sep 2011)**

**Q** We understand AD 94-13-10 (amendment 39-8951) which superceded AD 74-13-01 (amendment 39-1870) can be complied with (and thereby discontinue the recurring 100-hour requirement) by installing the Piper Part No 760 835 (Hi-Shear Rivet Replacement Kit). Where can we order this kit?

**A** Piper still builds these kits for Comanches. I've bought several of these kits over the years. Aviall is now the official Piper parts distributor. Contact them at 1 (800) 284-2556. The part number is very important. In addition, Webco has an AMOC which allows them to install it their way – others find it easier if they remove the vertical stabilizer and go in from the top.  
Pat Berry

**A** This is a very benign AD. A simple tail shake and a listen in a quiet shop will comply with the AD. I recommend not doing the "fix" if there is no problem to begin with. The test is not costly nor is it onerous. The repair kits are, however, fairly pricey, if you can find them, and you need four of them (one for each mounting bracket), plus the installation labor which can run upwards of 20 hours, especially if someone has never done it before. It's this repair versus a 30-second test every 100 hours. It is your airplane and your choice, but I don't see the benefit if the rivets aren't loose to begin with.  
Zach Grant

## **AD Listing (Feb 2012)**

**Q** I haven't been aware of any new ADs on PA-30s. Why doesn't the ICS publish a listing of all current ADs on the various models?

**A** Each airplane has a unique list of ADs due to different equipment installed and modifications. There is no practical way the ICS could create and keep current a listing of ADs for each Comanche that you could rely on in lieu of doing your own personalized AD search. ADs are available online at the FAA web site:

[http://rgl.faa.gov/Regulatory\\_and\\_Guidance\\_Library/rqAD.nsf/Frameset?OpenPage](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rqAD.nsf/Frameset?OpenPage)

This link will take you to the PA-30 airframe ADs, but you will also have to search the Lycoming Engine ADs, as well as appliance ADs for various items installed on your aircraft. I would strongly suggest that you invest a small sum to enroll the aircraft on ADLog (<http://www.adlog.com>). It will save you time and money in not paying for recurring research, as well as knowing the status of your airplane at a glance.

Zachary J. Grant